Location Information		System-Owned Portion							Customer-Owned Portion				Other Potential Sources of Lead		Additional Information to Assign Tap Monitoring Tiering			
			ystem-Owned Portion	If Non-Lead in	Service Line   Service Line Size   Basis of Material	rvice Line Describe the Field Date of Field	d Customer-Owned Portion	Service Line	Basis of Material	Vas Service Line  Describe the Field			ar	t Other Fittings nd Equipment			Does the Interior Building Plumbing Contain Copper	ng r
Service ID* Street Address* City*	Sensitive Population?*	Disadvantaged Neighborhood?*	Service Line Material Classification*	Column F, Was Material Ever Previously Lead?*	Installation Date (System Side) (System Side) (System Side)*  Classification (System Side)*  Verified Side)	Yerification Method Verification  (System Side) (System Side)		Installation Date (Customer Side)  Service Line Size (inches) (Customer Side)	Classification (Customer	Verification Method	e of Field Verification (Customer Side)	Notes (Customer Side)  Is there a Le Connector	?* the Service Line?* Se	onnected to the ervice Line that Contain Lead	uilding Type Connected   F to Service Line*   I	Jse Treatment Present?*	Solder Installed Before Your State's Lead Ban	
33 100 IRENE DR VINTON 70 100 ONEAL DR VINTON	No No		known - Material Unknow on-Lead - Other	w Don't know Don't know	Other No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow		Other No			vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know		ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
100 TRAPPER LN VINTON 101 COLLINS DR VINTON	No No	Yes No	on-Lead - Other on-Lead - Other	Don't know Don't know	Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead bake Installation record (e.g., tap cNo		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L	Jnknown Jnknown	No Unknown	No No
22 101 IRENE DR VINTON 51 101 ONEAL DR VINTON 55 101 TRAPPER LN VINTON	No No No	Yes Unl	known - Material Unknow known - Material Unknow n-Lead - Other		Other No Other No Installation date af No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Other No Installation date after lead by No Installation date after lead by No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L	Inknown Inknown Inknown	Unknown No No	No No No
1015 ODD FELLOWS VINTON 102 ONEAL DR VINTON	No No	Yes No	n-Lead - Copper n-Lead - Other	Don't know Don't know	Installation record No Installation record No		Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation date after lead band Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Bu Sir	uilding Ungle Family Residence U	Jnknown Jnknown	Unknown Unknown	No No
12 102 SHARP TURN R VINTON 16 102 WAYWOOD HII VINTON 73 103 COLLINS DR VINTON	No No No	Yes No	on-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation record (e.g., tap c No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L	Inknown Inknown Inknown	Unknown Unknown Unknown	No No No
36 103 IRENE DR VINTON 04 103 WAYWOOD HII VINTON	No No	Yes Unl Yes No	known - Material Unknow n-Lead - Other	w⊦Don't know Don't know	Other No Installation record No		Service line material classific Non-Lead - Plastic Service line material classific Non-Lead - Other		Field inspection Ye Installation record (e.g., tap c No	Customer self-identi 08/2024	24 Serv	Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
32 1033 BRITTLE ST VINTON 12 1033 KNOB HILL RD VINTON 48 1036 GOODVIEW R VINTON	No No No	Yes Unl	known - Material Unknow	Don't know w∣Don't know No	Installation record No Other No Installation date af No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other	/n	Other No Installation date after lead by No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence U	Inknown Inknown Inknown	Unknown Unknown No	No No No
104 CASCADE DR VINTON 104 IRENE DR VINTON	No No	Yes No	n-Lead - Other n-Lead - Other	Don't know No	Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap ( No Installation date after lead b; No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown No	No No
10 104 ONEAL DR VINTON 13 104 WAYWOOD HILVINTON 24 1040 LAMB FARM R GOODVIEW	No No No	Yes No		Don't know Don't know No	Installation record No Installation record No Installation date af No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Other No Installation record (e.g., tap c No Installation date after lead b: No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Jnknown	Unknown Unknown No	No No No
1045 PULPIT LN VINTON 20 1049 ODDFELLOWS VINTON	No No	Yes No	n-Lead - Other	Don't know Don't know	Installation record No Installation record No	Visual in an artist at 4 00/2024	Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir	ngle Family Residence L		Unknown Unknown	No No
23 105 COLLINS DR VINTON 54 105 IRENE DR VINTON 38 105 ONEAL DR VINTON	No No No	Yes Unl	on-Lead - Copper known - Material Unknow on-Lead - Other	No w Don't know Don't know	Field inspection Yes Other No Installation record No	Visual inspection at t 09/2024	1% Physical Verification Loca Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other	/n	Other No Field inspection Ye	o o S Visual inspection at t 06/2024	Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U		No Unknown Unknown	No No No
105 TRAPPER LN VINTON 105 WAYWOOD HILVINTON	No No	Yes No	n-Lead - Other n-Lead - Other	No Don't know	Installation date af No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead band Installation record (e.g., tap (No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	No Unknown	No No
33 1055 PULPIT LN VINTON 32 106 IRENE DR VINTON 48 106 ONEAL DR VINTON	No No No	Yes Unl	known - Material Unknow	Don't know w∣Don't know Don't know	Installation record No Other No Installation record No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow	/n	Other No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown Unknown Unknown	No No No
96 106 TRAPPER LN VINTON 91 106 WAYWOOD HII VINTON	No No	Yes No	on-Lead - Other on-Lead - Other	No No	Installation date af No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead band Installation record (e.g., tap c No	0	Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	No No	No No
72 1061 GOODVIEW R GOODVIEW 44 1062 LAMB FARM R VINTON 58 1064 TURNER BRAN GOODVIEW	No No No	Yes No	on-Lead - Copper on-Lead - Other on-Lead - Other	Don't know No No	Installation record No Installation date af No Installation date af No		Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead band Installation record (e.g., tap c No Installation date after lead band		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U		Unknown No No	No No No
107 COLLINS DR VINTON 107 IRENE DR VINTON	No No	Yes Not Yes Unl	n-Lead - Other known - Material Unknow		Installation record No Other No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation record (e.g., tap ( No Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
90 107 ONEAL DR VINTON 53 107 WAYWOOD HII VINTON 10 108 CASCADE DR VINTON	No No No	Yes No	n-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Non-Lead - Copper		Other No Installation record (e.g., tap c No Field inspection Ye	o S Visual inspection at t 09/2024	Serv	vice line material classific Don't Know vice line material classific Don't Know Physical Verification local Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Jnknown	Unknown Unknown Unknown	No No No
30 108 IRENE DR VINTON 48 108 ONEAL DR VINTON	No No	Yes Unl Yes No	known - Material Unknow on-Lead - Other		Other No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow	rn rn	Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
108 TRAPPER LN VINTON 12 108 WAYWOOD HILVINTON 22 1081 DREWRYS HILIVINTON	No No No	Yes No		No Don't know Don't know	Installation date af No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Non-Lead - Other		Installation date after lead band Installation record (e.g., tap c No Installation date after lead band		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	No Unknown Unknown	No No No
1083 ODDFELLOWS VINTON 109 IRENE DR VINTON	No No	Yes Not Yes Unl	n-Lead - Copper known - Material Unknow	Don't know w⊦Don't know	Installation record No Other No		Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation date after lead band Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
10 109 ONEAL DR VINTON 40 109 TRAPPER LN VINTON 58 109 WAYWOOD HILVINTON	No No No	Yes No		w Don't know No Don't know	Other No Installation date af No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Other No Installation date after lead by No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown No Unknown	No No No
3 1091 KNOB HILL RD VINTON 3 110 IRENE DR VINTON	No No	Yes Unl	known - Material Unknow known - Material Unknow	w Don't know w Don't know	Other No Other No		Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow	rn rn	Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
110 ONEAL DR VINTON 110 WAYWOOD HILVINTON 1100 ODDFELLOWS VINTON	No No No	Yes No	n-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Other No Installation record (e.g., tap c No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown Unknown Unknown	No No No
95 111 IRENE DR VINTON 98 111 ONEAL DR VINTON	No No	Yes Not Yes Unl	n-Lead - Other known - Material Unknow	Don't know	Field inspection Yes Other No	Visual inspection at t 06/2024	Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow	⁄n	Field inspection Ye Other No	Visual inspection at t 06/2024	24 Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
2 111 TRAPPER LN VINTON 2 111 WAYWOOD HILVINTON 4 1110 KNOB HILL RD VINTON	No No No	Yes No	n-Lead - Other n-Lead - Other known - Material Unknow	No Don't know ø⊦Don't know	Installation date af No Installation record No Other No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Plastic		Installation date after lead by No Installation record (e.g., tap c No Field inspection		Serv	vice line material classific Don't Know vice line material classific Don't Know Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	No Unknown Unknown	No No No
14 112 CASCADE DR VINTON 112 IRENE DR VINTON	No No	Yes Not Yes Unl	n-Lead - Other known - Material Unknow	No w∣Don't know	Installation date af No Other No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation date after lead band Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	No Unknown	No No
112 ONEAL DR VINTON 112 WAYWOOD HILVINTON 1121 ODD FELLOWS VINTON	No No No	Yes No	n-Lead - Other	Don't know Don't know Don't know	Field inspection Yes Installation record No Installation record No	Visual inspection at t 06/2024	Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Field inspection Ye Installation record (e.g., tap c No Installati		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Unilding		Unknown Unknown Unknown	No No No
113 IRENE DR VINTON 113 ONEAL DR VINTON	No No	Yes No	on-Lead - Other on-Lead - Other	Don't know Don't know	Field inspection Yes Field inspection Yes	Visual inspection at t 06/2024 Visual inspection at t 06/2024	Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Field inspection Yes	Visual inspection at t 06/2024 Visual inspection at t 06/2024	24 Serv 24 Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
34 113 WAYWOOD HII VINTON 56 1135 ODDFELLOWS VINTON 54 1138 WILDCAT RD VINTON	No No Yes - Daycare	Yes No	on-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation record (e.g., tap c No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	•	Inknown Inknown Inknown	Unknown Unknown Unknown	No No No
8 114 CASCADE DR VINTON 8 114 IRENE DR VINTON	No No	Yes No	on-Lead - Copper on-Lead - Other	Don't know Don't know	Installation record No Field inspection Yes	Visual inspection at t 06/2024	Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation date after lead band Other No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	No Unknown	No No
114 WAYWOOD HILVINTON 1141 EMERTS WAY VINTON 1142 SUBLETTE RD GOODVIEW	No No No	Yes No		Don't know Don't know w Don't know	Installation record No Installation record No Other No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow		Installation record (e.g., tap c No Installation record (e.g., tap c No Other No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown Unknown Unknown	No No No
3 114A ONEAL DR VINTON 3 114B ONEAL DR VINTON	No No	Yes Unl	known - Material Unknow known - Material Unknow	w Don't know	Other No Other No		Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow	vn	Other No		Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence	Inknown	Unknown Unknown	No No
74 115 IRENE DR VINTON 42 115 WAYWOOD HII VINTON 50 1150 DREWRYS HILI VINTON	No No	Yes No	n-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other Non-Lead - Other		Installation record (e.g., tap (No Installation date after lead b) No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown Unknown Unknown	No No
1152 TURNER BRANVINTON 1153 WILDCAT RD VINTON 14 116 IRENE DR VINTON	No No	Yes No		No Don't know Don't know	Installation record No Installation record No	Visual inspection at ±00/2024	Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow		Installation record (e.g., tap c No Installation record (e.g., tap c No Othor		Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know		uilding L	Inknown Inknown	No Unknown	No No
0 116 TRAPPER LN VINTON 9 1164 TRACKERS LN VINTON	No No	Yes No	n-Lead - Other	No Don't know	Field inspection Yes Installation date af No Installation record No	Visual inspection at t 06/2024	Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Other No Installation date after lead by No Installation record (e.g., tap ( No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L	Inknown Inknown Inknown	Unknown No Unknown	No No
58 1167 WILDCAT RD VINTON 92 116A ONEAL DR VINTON 45 116B ONEAL DR VINTON	No No	Yes Unl	n-Lead - Other known - Material Unknow known - Material Unknow		Installation record No Other No Other No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Unknown - Material Unknow	vn	Installation record (e.g., tap c No Other No Other No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	•	Jnknown Jnknown Jnknown	Unknown Unknown	No No
94 117 IRENE DR VINTON O1 117 WAYWOOD HILVINTON	No No	Yes No	on-Lead - Other	Don't know Don't know Don't know	Field inspection Yes Installation record No	Visual inspection at t 06/2024	Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other	/n	Other No Installation record (e.g., tap ( No		Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	Unknown Unknown Unknown	No No
118 CASCADE DR VINTON 118 WAYWOOD HILVINTON 1182 TRACKERS LN VINTON	No No No	Yes No		No Don't know Don't know	Installation date af No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Copper Service line material classific Non-Lead - Other		Installation date after lead b: No Field inspection Ye Installation record (e.g., tap c No	s Visual inspection at the mete	ter pit 1% P	vice line material classific Don't Know Physical Verification local Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L ngle Family Residence L ngle Family Residence L	Inknown	No Unknown Unknown	No No No
30 119 IRENE DR VINTON 97 119 WAYWOOD HII VINTON	No No	Yes No	on-Lead - Other on-Lead - Other	Don't know No	Field inspection Yes Installation date af No	Visual inspection at t 06/2024	Service line material classific Non-Lead - Plastic Service line material classific Non-Lead - Other		Field inspection Yes Installation date after lead by No	visual inspection at t 06/2024	24 Serv	Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown No	No No
6 120 IRENE DR VINTON 6 120 WAYWOOD HII VINTON 0 1201 ODD FELLOWS VINTON	No No No	Yes No		w Don't know Don't know Don't know	Other No Installation record No Installation record No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Copper Service line material classific Non-Lead - Other		Other No Field inspection Ye Installation record (e.g., tap ( No	visual inspection at the mete	ter pit 1% P	vice line material classific Don't Know Physical Verification local Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L ngle Family Residence L ngle Family Residence L	Jnknown	Unknown Unknown Unknown	No No No
121 IRENE DR VINTON 1224 GOODVIEW R GOODVIEW	No No	Yes No	n-Lead - Other n-Lead - Other	Don't know No	Field inspection Yes Installation date af No	Visual inspection at t 06/2024	Service line material classific Non-Lead - Plastic Service line material classific Non-Lead - Other		Field inspection Yes Installation date after lead by No	Visual inspection at t 06/2024	24 Serv	Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown No	No No
1228 EMERTS WAY VINTON 123 IRENE DR VINTON 123 WAYWOOD HILVINTON	NO NO NO	Yes Unl	on-Lead - Other known - Material Unknow on-Lead - Other	No w∣Don't know Don't know	Installation record No Other No Installation record No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Copper	/n	Installation record (e.g., tap c No Other No Field inspection Ye	o S Visual inspection at the mete	Serv	vice line material classific Don't Know vice line material classific Don't Know Physical Verification local Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence Ungle Family Residence Ungle Family Residence U	Inknown	No Unknown Unknown	NO No No
1265 GOODVIEW RIGOODVIEW 1286 GOODVIEW RIGOODVIEW	No No	Yes No	on-Lead - Other on-Lead - Copper	Don't know Don't know	Installation record No Installation record No		Service line material classific Non-Lead - Other Non-Lead - Other		Installation record (e.g., tap ( No Installation date after lead b; No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Sir	ngle Family Residence L ngle Family Residence L	Jnknown Jnknown	Unknown Unknown	No No
1325 GOODVIEW RIGOODVIEW 1351 GOODVIEW RIGOODVIEW 1374 RIVERMONT AVINTON	No No Yes - Daycare	Yes No	• • • • • • • • • • • • • • • • • • • •	Don't know Don't know w Don't know	Installation record No Installation record No Other No		Non-Lead - Other Non-Lead - Other Service line material classific Unknown - Material Unknow		Installation date after lead by No Installation date after lead by No Other No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence U	Inknown Inknown Inknown	Unknown Unknown Unknown	No No No
2 1425 GOODVIEW R GOODVIEW	Yes - School No	Yes No	known - Material Unknow n-Lead - Other	w Don't know No	Other No Installation date af No		Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other	vn	Other No Installation date after lead by No		Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Bu Sir	uilding Ungle Family Residence U	Jnknown Jnknown	Unknown No	No No
1545 GOODVIEW RIGOODVIEW  15462 STEWARTSVIVINTON  15610 STEWARTSVIVINTON	No No No	Yes No	on-Lead - Other on-Lead - Copper on-Lead - Other	No Don't know Don't know	Installation date af No Installation record No Installation record No		Service line material classific Non-Lead - Other  Non-Lead - Other  Service line material classific Non-Lead - Other		Installation date after lead band Installation date after lead band Installation date after lead band		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Bu	,	Inknown Inknown Inknown	No Unknown Unknown	No No No
4 15630 STEWARTSVIVINTON 4 15682 STEWARTSVIVINTON	No No	Yes No	on-Lead - Other on-Lead - Other	No No	Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap ( No Installation record (e.g., tap ( No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Bu Bu	uilding L uilding L	Jnknown Jnknown	No No	No No
5 15700 STEWARTSVIVINTON B 15720 STEWARTSVIVINTON 5 15725 STEWARTSVIVINTON	NO No No	Yes No		No Don't know Don't know	Installation date af No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead band Installation record (e.g., tap c No Installation record (e.g., tap c No	0	Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Bu	uilding U	Inknown Inknown Inknown	No Unknown Unknown	NO No No
15786 STEWARTSVIVINTON 15875 STEWARTSVIVINTON	No No	Yes No	on-Lead - Copper on-Lead - Other	Don't know Don't know	Installation record No Installation record No		Non-Lead - Other Service line material classific Non-Lead - Other		Installation date after lead band Installation record (e.g., tap c No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Bu Bu	uilding L uilding L	Jnknown Jnknown	Unknown Unknown	No No
77 1595 DREWRYS HILIVINTON 66 16000 STEWARTSVIVINTON 88 16090 STEWARTSVIVINTON	NO No No	Yes No	on-Lead - Other	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow Service line material classific Non-Lead - Other	/n	Other No Installation record (e.g., tap ( No Installation record (e.g., tap ( No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Bu	uilding U	Jnknown Jnknown Jnknown	Unknown Unknown Unknown	NO No No
16095 STEWARTSVIVINTON 16450 STEWARTSVIVINTON	No No	Yes No	on-Lead - Copper on-Lead - Other	Don't know Don't know	Installation record No Installation record No		Non-Lead - Copper Service line material classific Non-Lead - Other		Field inspection Yes Installation record (e.g., tap ( No	Visual inspection at the mete	ter pit 1% P Serv	Physical Verification locat Don't Know vice line material classific Don't Know	Don't Know Don't Know	Sir Ot	ngle Family Residence L ther L	Jnknown Jnknown	Unknown Unknown	No No
26 1693 DREWRYS HILIVINTON 56 1720 DREWRYS HILIVINTON 57 1731 DREWRYS HILIVINTON	No No No	Yes No	n-Lead - Copper	Don't know Don't know Don't know	Installation record No Installation record No Installation record No		Service line material classific Non-Lead - Other Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation date after lead b: No Installation record (e.g., tap c No		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L	Jnknown Jnknown Jnknown	Unknown Unknown Unknown	No No No
76 17599 STEWARTSVIVINTON 14 17671 STEWARTSVIVINTON 70 17720 STEWARTSVIVINTON	No No	Yes Not Yes Uni	n-Lead - Other known - Material Unknow	Don't know w∣Don't know	Installation record No Other No		Service line material classific Non-Lead - Other Service line material classific Unknown - Material Unknow	vn	Installation record (e.g., tap ( No		Serv Serv	vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know	Bu Bu	uilding Luilding L	Jnknown Jnknown	Unknown Unknown	No No
	No	Yes No	n-Lead - Other	Don't know Don't know No	Installation record No Installation record No Installation record No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation record (e.g., tap c No Installation record (e.g., tap c No	0	Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	ngle Family Residence L	Inknown Inknown Inknown	Unknown Unknown No	No No
17720 STEWARTS VIVINTON 22 1799 DREWRYS HILI VINTON 28 1845 DREWRYS HILI VINTON	No	Yes No	n-Lead - Other												-			
1799 DREWRYS HILIVINTON	No No No	Yes No	n-Lead - Other	No Don't know	Installation record No Installation record No Other No		Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other Service line material classific Non-Lead - Other		Installation record (e.g., tap c No Installation record (e.g., tap c No Installation date after lead band		Serv	vice line material classific Don't Know vice line material classific Don't Know vice line material classific Don't Know	Don't Know Don't Know Don't Know	Sir	•	Jnknown Jnknown Jnknown	No Unknown Unknown	No No